

STANDARD DEPARTURE
ROUTES - INSTRUMENT
(SID)

FRANKFURT MAIN
RWY 25L

SIDs with Route Designator **HOTEL**

For Operational Runway Use Concept see AD 2 EDDF 5-7-1 and 5-7-2

Pilots of GPS/FMS-RNAV-equipped aircraft shall, if possible, use the supplementary GPS/FMS RNAV procedures which are described following the text "GPS / FMS RNAV;" and charted in addition on "CHART - INSTRUMENT (OVERLAY)". When using these supplementary GPS/FMS RNAV procedures, the pilot shall check and ensure that the underlying conventional flight procedures are adhered to by monitoring the information of the ground-based navigation aids. The ground-based navigation aids required for the use of the respective conventional flight procedure and the associated aircraft equipment shall remain in operation at all times.

Designator	Route	After Take-Off		Remarks
		Climb to	Contact	
1	2	3	4	5
OBOKA 2H	OBOKA TWO HOTEL On RWY track to 5.2 DME FFM/2.2 DME FRD; LT, direct VFM (MAX IAS 200 KT until VFM); on track 194° to 10.1 DME FFM/7.2 DME FRD. RT (MAX IAS 230 KT), to PABVI (△) (MAX IAS 230 KT), to SIVDO (△); to KUPIP (△); to MASIR (△); to RAVKI (△); to DITAM (△); to OBOKA (△). Cross 5.2 DME FFM/2.2 DME FRD at or above 800. Cross 10.1 DME FFM/7.2 DME FRD at or above 2500. GPS/FMS RNAV: DF980[A800+; L] - VFM[K200-] - DF172[A2500+] - PABVI[K230-] - SIVDO - KUPIP - MASIR - RAVKI - DITAM - OBOKA. Recommended Path Terminator for initial departure turn: Direct to a Fix (DF).	FL 70	Langen Radar 120.155*	1. PDG 8.5% / 520 ft/NM or more until passing 800, then PDG 4.5% / 275 ft/ NM or more until passing 2500 due to airspace structure. If unable to comply, advise EDDF DELIVERY prior to start-up. 2. After 10.1 DME FFM (7.2 DME FRD) RNAV 5 equipment necessary. 3. Flights have to be able to cross OBOKA at FL 170 or above except flights to EDDK. If unable to comply, advise EDDF DELIVERY prior to start-up.
MARUN 5H	MARUN FIVE HOTEL On RWY track to 5.2 DME FFM/2.2 DME FRD; LT, direct VFM (MAX IAS 200 KT until VFM); on track 194° to 10.1 DME FFM/7.2 DME FRD. RT (MAX IAS 230 KT), to ROXAP (MAX IAS 230 KT) (△); to ADEVO(△) to LISKU (△); to TABUM (△) to LIKSI (△); to LORPA (△) to MARUN (△). Cross 5.2 DME FFM/2.2 DME FRD at or above 800. Cross 10.1 DME FFM/7.2 DME FRD at or above 2500. Cross ADEVO at or above 6000. GPS/FMS RNAV: DF980[A800+; L] - VFM[K200-] - DF180[A2500+] - ROXAP[K230-] - ADEVO[A6000+] - LISKU - TABUM - LIKSI - LORPA - MARUN. Recommended Path Terminator for initial departure turn: Direct to a Fix (DF).			1. PDG 8.5% / 520 ft/NM or more until passing 800, then PDG 6.8% / 415 ft/ NM or more until passing 6000 due to operational requirements. If unable to comply, advise EDDF DELIVERY prior to start-up. 2. After 10.1 DME FFM (7.2 DME FRD) RNAV 5 equipment necessary.
TOBAK 5H	TOBAK FIVE HOTEL On RWY track to 5.2 DME FFM/2.2 DME FRD; LT, direct VFM (MAX IAS 200 KT until VFM); on track 194° to 10.1 DME FFM/7.2 DME FRD. RT (MAX IAS 230 KT), to ROXAP (MAX IAS 230 KT)(△); to ADEVO(△) to LISKU (△); to TABUM (△); to TESGA (△); to TOBAK (△). Cross 5.2 DME FFM/2.2 DME FRD at or above 800. Cross 10.1 DME FFM/7.2 DME FRD at or above 2500. Cross ADEVO at or above 6000. GPS/FMS RNAV: DF980[A800+; L] - VFM[K200-] -DF180[A2500+] - ROXAP[K230-] - ADEVO[A6000+] - LISKU - TABUM - TESGA - TOBAK. Recommended Path Terminator for initial departure turn: Direct to a Fix (DF).			

(Sample: DF980 fly-over way point)

* Departure frequency may deviate from the frequency published.
Check ATIS for current departure frequency.

Contact LANGEN RADAR when advised by Tower!