



INSTRUMENT APPROACH CHART - ICAO

ULYANOVSK, RUSSIA
 VOSTOCHNY
 RNP RWY 02



MISSED APPROACH
Climb straight ahead to 1000' (230),
turn RIGHT to LW602 climbing to
1900' (505) or above, then to
LW502 or as instructed by ATC.



1 TRANSITION LEVEL:
- FL050 when QNH is 977 hPa (733mm mercury column) or above;
- FL060 when QNH is less than 977 hPa (733mm mercury column).

WARNING
Visual manoeuvring north-west of the aerodrome is PROHIBITED.