

NUERNBERG
RWY 10

STANDARD INSTRUMENT DEPARTURE
ROUTES (SID)

Designator	Route	After Take-Off		Procedure remarks
		Climb to	Contact	
NUB 1A	NUERNBERG ONE ALPHA On R095 NUB to <u>DN490</u> ; RT, direct to VOR NUB. Cross NUB at or above 6000. MAX IAS 250 KT until crossing NUB.	6000 ft	MUENCHEN RADAR 129.525 Contact Muenchen Radar when advised by Tower.	1. For Non-RNAV-1 equipped aircraft only. 2. For RNAV-1 equipped aircraft not to be filed in flightplan, by ATC only.