

STAR (CAT H)

General remark
Procedures outside controlled airspace.

OZE 1K

Proceed via OZE VOR – TR 258° (RDL 258 OZE VOR), crossing RDL 352 TNT VOR, turn left to intercept and follow RDL 347 TNT VOR bound to BAMOV.

MEA: 10000 FT

VIC 3K

Proceed via VIC VOR TR 314° (RDL 314 VIC VOR) bound to TNT VOR/DME.

MEA: 10000 FT