


Transition Altitude 4000

MISSED APPROACH:

Climb on R 037 LMO. At 2000ft turn left to LMO and hold. Arrange to pass LMO 4000ft or above.



OCA / H		A	B	C	D
STRAIGHT - IN APPROACH	FT	820 (806)			
CIRCLING EAST OF RWY	FT	820 (806)	900 (886)	1400 (1386)	

DIST	7DME	6DME	5DME	4DME
ALT (HEIGHT)	1900 (1886)	1600 (1586)	1300 (1286)	1000 (986)

SPEED	KT	100	130	160	190
RATE OF DESCENT	FT/MIN	507	659	811	963

Change: Magnetic Variation