

EFRO OMNIDIRECTIONAL DEPARTURES			
RWY	PROC	Controlling OBST	
		Phase	ELEV FT / BRG GEO / DIST NM
03	Climb straight ahead until MNM turning ALT 1010 FT.	PDG	NIL
		TNA	NIL
21	Climb straight ahead until MNM turning ALT 1030 FT.	PDG	NIL
		TNA	NIL

ADDITIONAL INFORMATION FOR ALL RUNWAYS	
<b>SQUAWK</b>	WHEN LINING UP SQUAWK THE ASSIGNED CODE
<b>NOISE ABATEMENT</b>	AFTER TAKE-OFF CLIMB AS RAPIDLY AS PRACTICABLE TO AT LEAST 2000 FT ABOVE AD ELEV
<b>RADIO CONTACT</b>	MAINTAIN TWR FREQ UNTIL 2000 FT, THEN CONTACT ROVANIEMI RADAR FREQ 129.900

EFRO RWY 03 CLOSE-IN OBSTACLES		
NR	COORD	ELEV FT
	NIL	

EFRO RWY 21 CLOSE-IN OBSTACLES		
NR	COORD	ELEV FT
	NIL	