


STANDARD ARRIVAL CHART
INSTRUMENT (STAR) - ICAO

SOCHI, RUSSIA
SOCHI
RNAV RWY 02

TRANSITION
LEVEL : 1

PZ - 90.02 coordinates
PZ - 90.11 coordinates



APPROACH	124.600
RADAR	119.700
START	135.800

1 TRANSITION LEVEL:
 - FL150 when QNH is 977 hPa (733mm mercury column) or above;
 - FL160 when QNH is less than 977 hPa (733mm mercury column).

BEARINGS AND TRACKS ARE MAGNETIC ALTITUDES AND ELEVATIONS IN FEET HEIGHTS IN METRES DISTANCES IN KILOMETRES

Alt set: -QNH(QFE on req); -hPa(mm on req).

CHANGE: Call sign, URP721